

M-SURE T1 Data Output Remote Display



- Remote plug-in display, compatible with any T1 output M-SURE gauge
- Simple mounting using magnetic back or mounting plate supplied
- Fit the display in a convenient location for user and operation
- Add ABS/INC and fraction readout functionality to any compatible gauge. The attached gauge will require a battery to power the unit
- Please note the connected gauge needs to be set to mm reading. The remote can be toggled between mm and inch fractions
- Standard functions: Inch/mm Conversion, Zero Reset, Low Battery Alert, On/Off, ABS/INC, Inch Fraction Resolution

Specifications

	MS-620-001
Data Input Type	M-SURE Type 1
Cable Length	2000mm
Character Height	12mm
Battery	CR2032 3v Lithium Cell

Applications



Dimensions



	a	g
MS-620-001	57	18

All dimensions in mm