

M-SURE T1 Data Output USB Interface



The M-SURE T1 data USB interface features a status LED that flashes to indicate the measurement device is connected. Pressing the DATA button on the interface will paste the displayed information directly into any Microsoft Windows-based software such as Excel. Wherever you position the cursor the displayed value will be inserted. There is also a carriage return to skip to the next line/cell in preparation for the next value.

The units can be changed using the MM/INCH button, this will also insert the current unit into line/cell. The gauge can also be set to zero using the ZERO button on the interface.

A foot-operated or remote switch can be connected to the interface to act as the data capture button. The attached gauge will require a battery to power the unit.


An Auto mode will capture the value 8 times per second and automatically paste the result. No driver or additional software is required.

Please contact us for bespoke and multichannel options.

Specifications

	MS-601-010
Data Input Type	M-SURE Type 1
PC Connection	USB Type A
USB Cable Length	2000mm
Interface to Gauge Cable Length	400mm

Applications



Dimensions



All dimensions in mm

	a	b
MS-601-010	64	37